

Michael Falk Director Compliance Gas Operations 6111 Bollinger Canyon Rd. San Ramon, CA 94583 Phone: 925.244.3276 E-mail: mdfl@pge.com

February 29, 2016

Mr. Ken Bruno Gas Safety and Reliability Branch Safety and Enforcement Division California Public Utilities Commission 505 Van Ness Avenue San Francisco, CA 94102

Re: State of California – Public Utilities Commission General Order 112 Audit – PG&E's Topock District

Dear Mr. Bruno:

The Safety and Enforcement Division (SED) of the CPUC conducted a General Order 112 audit of PG&E's Topock District from October 20-22, 2015. On January 29, 2016, the SED submitted their audit report, identifying violations and findings. Attached is PG&E's response to the CPUC audit report.

Please contact Glen Allen at (925) 278-3462 or gmad@pge.com for any questions you may have regarding this response.

Sincerely,

/**S**/ Michael Falk

Attachments

cc: Willard Lam, CPUC Aimee Cauguiran, CPUC Dennis Lee, CPUC Larry Deniston, PG&E Sumeet Singh, PG&E

ype						
ernal,						Associated Attachment
-	Finding #			Finding	Response	(File Name)
NOV s Internal	1			ts findings from the internal review it conducted of Topock District (District). Some c refore violations of Title 49 Code of Federal Regulations (CFR), §192.13(c) or §192.605		. corrective Att 1_Updated - Topock District 2015 Internal Audi Findings.pdf
Findings		-		Table 1 lists all of the violations from PG&E's internal review.	(a). SED is aware that actions taken and the remediation status. Opdates have been nightighted in yellow.	i indings.pui
U			0 1			
				of the items by the time of this letter. Please provide an update on the corrective s	tatus on the items that	
		were pending as of October 22,	2015.			
VOV		1. Title 49 CFR §192.605(a) state			As stated in the finding, on 11/10/14, the District discovered a below adequate pipe to soil reading of -834 millivolts	
			d follow for each pipeline	e, a manual of written procedures for conducting operations and maintenance activi		
		response."			plan had been created after the 2014 reading. This ETS was read again on 1/20/16 with an adequate pipe to soil rea mv. Attached, please find Attachment 2 - L-300B MP 2.10 Read.	ading of -ate
		1.1 Gas Standard O-16, Section	5, Paragraph (B)(3), state	s:		
				is (or expected to be) over 60 days, the [CPA Follow-Up Action Plan] form must be us		
		60 calendar days from the date	the CPA is found below a	adequate levels of protection"	generated and sent to appropriate parties, alerting them of the need to initiate action plans and to make in a timely	·
		During a review of the District's	corrosion records SED d	liscovered the "CPA Follow-Up Action Plan" form (Action Plan) was created late for E	any subsequent updates to the action plans, including scheduling of work requests. In addition, all local mechanics l tail-boarded on the Action Plan Procedures. Attached, please find Attachment 3 - Topock Tailboard.	nave been
		-		District discovered a below adequate pipe to soil reading of -834 millivolts (mV) at ET.		
		2/20/15, the District recorded a	subsequent reading of -9	993 mV. However, no Action Plan was created, thus violating PG&E's Gas Standard C	J-16 and subsequently 49	
		CFR §192.605(a).				
OC	1	-		erous pipe-to-soil readings to have below adequate protection (see Table 2). SED is a		
				s (MP 25 and MP 40), however, SED still considers these below adequate pipe-to-soil equate since the beginning of 2015. PG&E's temporary cathodic protection no longe		Att 5_MP 40 Work Request_CONF.pdf Att 6_Topock Updated ETS Reads_CONF.xlsx
				on. Please provide SED with an update for the ETS locations listed in Table 2 and the		
		repairs for the stolen rectifiers.			2016. The project will install a new anode as well as the rectifier at PLS-1A. Attached, please find Attachment 5 - MI	IP 40 Work
		Item # Field Visit Type Line 1 ETS Read Ne	e Mile Poir edles Tap 0.7	-865 mV	Request.	
		2 Rectifier A	0.24	1.3 VDC; 0.0A (bad anode wire)	Attached, please find Attachment 6 - Topock Updated ETS Reads. Those reads that are low have been highlighted in	n vellow
		3 ETS Read B	0.24	-300 mV (due to down rectifier)	along with the status of the associated remediation.	
		4 ETS Read A	0.32	-803 mV		
		5 ETS Read B 6 ETS Read B	0.95 2.93	-803 mV -601 mV		
		7 ETS Read B	4.97	-754 mV		
		8 ETS Read B	13.6	-728 mV		
		9 ETS Read A	16.33	-708 mV		
		9 ETS Read A 10 ETS Read B	17.9	-700 mV		
		9 ETS Read A 10 ETS Read B 11 ETS Read B	17.9 18.9	-700 mV -671 mV		
		9 ETS Read A 10 ETS Read B	17.9	-700 mV		
		9ETS ReadA10ETS ReadB11ETS ReadB12ETS ReadA	17.9 18.9 20.3	-700 mV -671 mV -700mV		
		9ETS ReadA10ETS ReadB11ETS ReadB12ETS ReadA13ETS ReadA14ETS ReadA15ETS ReadB	17.9 18.9 20.3 21.23 22.14 25.38	-700 mV -671 mV -700mV -587 mV -690 mV -681 mV		
		9ETS ReadA10ETS ReadB11ETS ReadB12ETS ReadA13ETS ReadA14ETS ReadA15ETS ReadB16ETS ReadA	17.9 18.9 20.3 21.23 22.14 25.38 26	-700 mV -671 mV -700mV -587 mV -690 mV -681 mV -601 mV		
		9ETS ReadA10ETS ReadB11ETS ReadB12ETS ReadA13ETS ReadA14ETS ReadA15ETS ReadB16ETS ReadA17ETS ReadA	17.9 18.9 20.3 21.23 22.14 25.38 26 30.79	-700 mV -671 mV -700mV -587 mV -690 mV -681 mV -601 mV -567 mV		
		9ETS ReadA10ETS ReadB11ETS ReadB12ETS ReadA13ETS ReadA14ETS ReadA15ETS ReadB16ETS ReadA	17.9 18.9 20.3 21.23 22.14 25.38 26	-700 mV -671 mV -700mV -587 mV -690 mV -681 mV -601 mV		
		9ETS ReadA10ETS ReadB11ETS ReadA12ETS ReadA13ETS ReadA14ETS ReadA15ETS ReadB16ETS ReadA17ETS ReadA18ETS ReadB19ETS ReadB20ETS ReadB	17.9 18.9 20.3 21.23 22.14 25.38 26 30.79 30.4 33.31 35.43	-700 mV -671 mV -700mV -587 mV -690 mV -681 mV -601 mV -567 mV -643 mV -737 mV -788 mV		
		9ETS ReadA10ETS ReadB11ETS ReadA12ETS ReadA13ETS ReadA14ETS ReadA15ETS ReadB16ETS ReadA17ETS ReadA18ETS ReadB19ETS ReadB20ETS ReadB21ETS ReadA	17.9 18.9 20.3 21.23 22.14 25.38 26 30.79 30.4 33.31 35.43 36.62	-700 mV -671 mV -700mV -587 mV -690 mV -681 mV -601 mV -567 mV -643 mV -737 mV -768 mV -567 mV		
		9ETS ReadA10ETS ReadB11ETS ReadA12ETS ReadA13ETS ReadA14ETS ReadA15ETS ReadB16ETS ReadA17ETS ReadA18ETS ReadB20ETS ReadB21ETS ReadA22ETS ReadA	17.9 18.9 20.3 21.23 22.14 25.38 26 30.79 30.4 33.31 35.43 36.62 37.13	-700 mV -671 mV -700mV -587 mV -690 mV -681 mV -601 mV -567 mV -643 mV -737 mV -768 mV -567 mV -562 mV		
		9ETS ReadA10ETS ReadB11ETS ReadA12ETS ReadA13ETS ReadA14ETS ReadA15ETS ReadB16ETS ReadA17ETS ReadA18ETS ReadB19ETS ReadB20ETS ReadB21ETS ReadA	17.9 18.9 20.3 21.23 22.14 25.38 26 30.79 30.4 33.31 35.43 36.62	-700 mV -671 mV -700mV -587 mV -690 mV -681 mV -601 mV -567 mV -643 mV -737 mV -768 mV -567 mV		
		9ETS ReadA10ETS ReadB11ETS ReadA12ETS ReadA13ETS ReadA14ETS ReadA15ETS ReadA16ETS ReadA17ETS ReadA18ETS ReadB20ETS ReadB21ETS ReadA22ETS ReadA23ETS ReadA	17.9 18.9 20.3 21.23 22.14 25.38 26 30.79 30.4 33.31 35.43 36.62 37.13 38.2	-700 mV -671 mV -700mV -587 mV -690 mV -681 mV -661 mV -661 mV -567 mV -643 mV -737 mV -768 mV -567 mV -562 mV -620 mV		
		9ETS ReadA10ETS ReadB11ETS ReadA12ETS ReadA13ETS ReadA14ETS ReadA15ETS ReadA16ETS ReadA17ETS ReadA18ETS ReadB20ETS ReadB21ETS ReadA22ETS ReadA23ETS ReadA24ETS ReadB25ETS ReadA26ETS ReadB	17.9 18.9 20.3 21.23 22.14 25.38 26 30.79 30.4 33.31 35.43 36.62 37.13 38.2 42.6 44.12 44.54	-700 mV -671 mV -700mV -587 mV -690 mV -681 mV -601 mV -661 mV -567 mV -643 mV -737 mV -768 mV -567 mV -562 mV -620 mV -649 mV -649 mV -823 mV		
		9ETS ReadA10ETS ReadB11ETS ReadA12ETS ReadA13ETS ReadA14ETS ReadA15ETS ReadA16ETS ReadA17ETS ReadB19ETS ReadB20ETS ReadB21ETS ReadA23ETS ReadA24ETS ReadB25ETS ReadB26ETS ReadB27ETS ReadA	17.9 18.9 20.3 21.23 22.14 25.38 26 30.79 30.4 33.31 35.43 36.62 37.13 38.2 42.6 44.12 44.54 52.03	-700 mV -671 mV -700mV -587 mV -690 mV -681 mV -601 mV -567 mV -643 mV -737 mV -768 mV -567 mV -562 mV -562 mV -649 mV -823 mV -829 mV		
DC		9ETS ReadA10ETS ReadB11ETS ReadA12ETS ReadA13ETS ReadA14ETS ReadA15ETS ReadA16ETS ReadA17ETS ReadB19ETS ReadB20ETS ReadA23ETS ReadA24ETS ReadA25ETS ReadB26ETS ReadB27ETS ReadA20ETS ReadA21ETS ReadB22ETS ReadA23ETS ReadB24ETS ReadB25ETS ReadA26ETS ReadB27ETS ReadADuring a field visit to a rectifier	17.9 18.9 20.3 21.23 22.14 25.38 26 30.79 30.4 33.31 35.43 36.62 37.13 38.2 42.6 44.12 44.54 52.03 at L-300B MP 40.49, SED r	-700 mV -671 mV -700mV -587 mV -690 mV -681 mV -601 mV -567 mV -643 mV -737 mV -768 mV -737 mV -768 mV -567 mV -562 mV -562 mV -620 mV -766mV -649 mV -823 mV -823 mV -829 mV noticed the smell of natural gas present in the area. Upon investigation, SED determ	nined the cause of the odor Work to repair the leaking relief valve at PLS-1B were completed on 10/21/2015 by injecting the valve with sealant. ide SED with an update on please find Attachment 7 - PLS-1B Closed Work Request.	Attached, Att 7_PLS-1B Closed Work Request_CONF.pdf

## 2015 Topock District Audit Findings and Responses

Finding				
Туре				
[Internal,				Associated Attachment
NOV, AOC]	Finding #	Finding	Response	(File Name)
AOC		The soil embankment eroded past the concrete layer protecting the pipeline, exposing an approximately 2.5 foot section of the pipeline coating. Please provide SED with the last inspection of the exposed section prior to SED's 10/21/2015 visit. Additionally, provide a status update on the District's remediation of the said exposed section of L-300A.		Att_8 Ground Patrol Report_CONF.pdf Att_9 Exposed Pipe Work Request_CONF.pdf