



2.MILES OF MAINS IN SYSTEM AT END OF YEAR												
MATERIAL	UNKNOWN	2" OR LESS	OVER 2" THRU 4"	OVER 4" THRU 8"	OVER 8" THRU 12"	OVER 12"	SYSTEM TOTALS					
STEEL	0	0	0.01	0	0	0	0.01					
DUCTILE IRON	0	0	0	0	0	0	0					
COPPER	0	0	0	0	0	0	0					
CAST/WROUGHT IRON	0	0	0	0	0	0	0					
PLASTIC PVC	0	0	0	0	0	0	0					
PLASTIC PE	0	31.57	3.57	5.66	0	0	40.8					
PLASTIC ABS	0	0	0	0	0	0	0					
PLASTIC OTHER	0	0	0	0	0	0	0					
OTHER	0	0	0	0	0	0	0					
RECONDITIONED CAST IRON	0	0	0	0	0	0	0					
TOTAL	0	31.57	3.58	5.66	0	0	40.81					
Describe Other Material:												
3.NUMBER OF SERVICES IN SYSTEM AT END OF YEAR												
											AVERAGE SERVICE LENGTH: 93.84	
MATERIAL	UNKNOWN	1" OR LESS	OVER 1" THRU 2"	OVER 2" THRU 4"	OVER 4" THRU 8"	OVER 8"	SYSTEM TOTALS					
STEEL	0	0	0	0	0	0	0					
DUCTILE IRON	0	0	0	0	0	0	0					
COPPER	0	0	0	0	0	0	0					
CAST/WROUGHT IRON	0	0	0	0	0	0	0					
PLASTIC PVC	0	0	0	0	0	0	0					
PLASTIC PE	0	1662	0	0	0	0	1662					
PLASTIC ABS	0	0	0	0	0	0	0					
PLASTIC OTHER	0	0	0	0	0	0	0					
OTHER	0	0	0	0	0	0	0					
RECONDITIONED CAST IRON	0	0	0	0	0	0	0					
TOTAL	0	1662	0	0	0	0	1662					
Describe Other Material:												
4.MILES OF MAIN AND NUMBER OF SERVICES BY DECADE OF INSTALLATION												
	UNKNOWN	PRE-1940	1940-1949	1950-1959	1960-1969	1970-1979	1980-1989	1990-1999	2000-2009	2010-2019	2020-2029	TOTAL

MILES OF MAIN	0	0	0	0	0	0	0	0	0	33.65	7.16		40.81
NUMBER OF SERVICES	0	0	0	0	0	0	0	0	0	1249	413		1662

**PART C - TOTAL LEAKS AND HAZARDOUS LEAKS ELIMINATED/REPAIRED DURING THE YEAR**

CAUSE OF LEAK	MAINS		SERVICES	
	TOTAL	HAZARDOUS	TOTAL	HAZARDOUS
CORROSION FAILURE	0	0	0	0
NATURAL FORCE DAMAGE	0	0	0	0
EXCAVATION DAMAGE	0	0	2	2
OTHER OUTSIDE FORCE DAMAGE	0	0	0	0
PIPE, WELD OR JOINT FAILURE	0	0	0	0
EQUIPMENT FAILURE	0	0	0	0
INCORRECT OPERATIONS	0	0	0	0
OTHER CAUSE	0	0	0	0

NUMBER OF KNOWN SYSTEM LEAKS AT END OF YEAR SCHEDULED FOR REPAIR : 0

**PART D - EXCAVATION DAMAGE**

1. TOTAL NUMBER OF EXCAVATION DAMAGES BY APPARENT ROOT CAUSE: 2

a. One-Call Notification Practices Not Sufficient: 2

b. Locating Practices Not Sufficient: 0

c. Excavation Practices Not Sufficient: 0

d. Other: 0

2. NUMBER OF EXCAVATION TICKETS : 371

**PART E - EXCESS FLOW VALUE (EFV) AND SERVICE VALVE DATA**

Total Number Of Services with EFV Installed During Year: 56

Estimated Number Of Services with EFV In the System At End Of Year: 300

\* Total Number of Manual Service Line Shut-off Valves Installed During Year: 0

\* Estimated Number of Services with Manual Service Line Shut-off Valves Installed in the System at End of Year: 0

*\*These questions were added to the report in 2017.*

**PART F - LEAKS ON FEDERAL LAND**

TOTAL NUMBER OF LEAKS ON FEDERAL LAND REPAIRED OR SCHEDULED TO REPAIR: 0

**PART G-PERCENT OF UNACCOUNTED FOR GAS**

UNACCOUNTED FOR GAS AS A PERCENT OF TOTAL CONSUMPTION FOR THE 12 MONTHS ENDING JUNE 30 OF THE REPORTING YEAR.

[(PURCHASED GAS + PRODUCED GAS) MINUS (CUSTOMER USE + COMPANY USE + APPROPRIATE ADJUSTMENTS)] DIVIDED BY (CUSTOMER USE + COMPANY USE + APPROPRIATE ADJUSTMENTS) TIMES 100 EQUALS PERCENT UNACCOUNTED FOR.

FOR YEAR ENDING 6/30: 1.75%

**PART H - ADDITIONAL INFORMATION**

**PART I - PREPARER**

Michael Lamond, Administrator (Preparer's Name and Title)	(209) 772-3006 _____ (Area Code and Telephone Number)
mike@alpinenaturalgas.com (Preparer's email address)	(209) 772-3008 _____ (Area Code and Facsimile Number)