



A  Sempra Energy utility®

San Diego Gas & Electric

General Order 174

2018 Annual Substation Inspection

Program Report

July 1, 2019

GO 174 Report Summarizing Completed and Past Due Inspections for 2018

Inspection Type	Completed*	Past Due**	Notes
Weekly Security Inspection	6,911	0	
Monthly Security Inspection	958	0	
Annual Infrared Inspection	139	0	

**Completed - Actual number of GO 174 inspections performed for the reporting period. Does not include outstanding inspections from prior reporting periods.*

***Past Due - The number of GO 174 inspections not performed for the reporting period. Does not include outstanding inspections from prior reporting periods.*